

Step-By-Step

- Update main software to accept MTConnect Adapter and Configure CNC Parameters. (A2 for Lathe. A3 for Mill) (Call Mazak Service)
- Order SMART Adapter (Part # CCWMPD0740E) (Customer Responsibility)
- Hook up CNC to Ethernet Network (Customer Responsibility)
- Install MTConnect SMART Adapter on customer supplied PC. Request License via email. (Customer Responsibility)
- Install License file and configure Adapter. (Customer Responsibility)
- 6 Install MTConnect AGENT on stand alone PC and configure. (Customer Responsibility)
- Evaluate and purchase 3rd party monitoring software. (Customer responsibility) Visit <u>www.mtconnect.org</u> for 3rd party product references





Step-By-Step

- Update main software to accept MTConnect Adapter and Configure CNC Parameters. (A7 for QTS. A8 for VCS) (Call Mazak Service)
- Order SMART Adapter (Part # CCWMPD0740E) (Customer Responsibility)
- Hook up CNC to Ethernet Network (Customer Responsibility)
- Install MTConnect SMART Adapter on customer supplied PC. Request License via email. (Customer Responsibility)
- Install License file and configure Adapter. (Customer Responsibility)
- 6 Install MTConnect AGENT on stand alone PC and configure. (Customer Responsibility)
- Evaluate and purchase 3rd party monitoring software. (Customer responsibility) Visit <u>www.mtconnect.org</u> for 3rd party product references



MAZAK FUSION CNC

Step-By-Step

- Confirm Main software for CNC is at minimum required to support MTConnect Adapter software. (Call Mazak Service)
- Purchase MTConnect Adapter software for your make and model Mazak CNC. (Customer Responsibility)
 Part#s Win95 = CCWMPD0720E / Win2k = CCWMPD0730E
- Install and test the MTConnect Adapter and AGENT software. (Call Mazak Service)
- A Network CNC to factory network. ("2 PCMCIA Slot Option" required. Stnd on most Fusion CNCs) (Customer Responsibility)
 - * Fusion CNC controls require purchase of a 16 bit PCMCIA Network Interface Card (NIC).
- 5 Evaluate and purchase Third Party dashboard or cloud based software solutions (Customer Responsibility)

Visit www.mtconnect.org for 3rd party product references



Adapter for MAZAK MATRIX (1) CNC Step-By-Step

- Confirm Main software for CNC is at minimum required to support MTConnect Adapter software. (Call Mazak Service)
- Purchase MTConnect Adapter software for your make and model Mazak CNC. (Customer Responsibility)
 Part# CCWMPD0690E
- Install and test the MTConnect Adapter and AGENT software. (Call Mazak Service)
- A Network CNC to factory network. (Customer Responsibility)
- 5 Evaluate and purchase Third Party dashboard or cloud based software solutions (Customer Responsibility)

Visit www.mtconnect.org for 3rd party product references



Adapter for MAZAK MATRIX (2) CNC Step-By-Step

- Purchase MTConnect Adapter software for your make and model Mazak CNC. (Customer Responsibility)
 Part# CCWMPD0700E
- Install and test the MTConnect Adapter and AGENT software.
 (Call Mazak Service)
- Network CNC to factory network. (Customer Responsibility)
- Evaluate and purchase Third Party dashboard or cloud based software solutions (Customer Responsibility)

Visit www.mtconnect.org for 3rd party product references



Step-By-Step

- Purchase MTConnect Adapter software. (Customer Responsibility) Part# CCWMPD0600E
- 2 Install and test the MTConnect Adapter and AGENT software. (Call Mazak Service)
- Network CNC to factory network. (Customer Responsibility)
- Evaluate and purchase Third Party dashboard or cloud based software solutions (Customer Responsibility)

Visit www.mtconnect.org for 3rd party product references

